



C009 Focus on Safety: Marking of Padeyes, Containers and other lifting equipment

Padeye Marking: (Easy ID For Inspection – Does not cover the item in paint)

Marking Design ‘Paint up to Box’ (Paint Black box using stencil and then stencil Data on that)



Container / Basket / Skid Marking:



(Easy ID For Inspection – Does not cover the item in paint – Makes Drops on Containers, Baskets, Skids more apparent – Reduces the need for Container Drops lift checklist paperwork if the checklist is on the side of the container with highlighted areas – part of Drops / HSE Audit will be to renew stickers)

The Large ID Box can be Painted on or provided as a Sticker (in several sizes for different type of skid / basket)

- Makes Inspections Quicker and more accurate
- Makes Operator aware of known lifting weight and Unit SWL
- Easy color code verification – does not just highlight Lifting points – encompasses the entire unit
- Highlights the importance of Drops on any item to be lifted.